

Progressive Materials Product Equipment QuickSheet

| | High Solids | Low Solids |
|-----------------|---|---|
| Colors | White - HS 3201 | Light Gray - HS 3203 |
| | Tan HS 3202 | Dark Gray - HS 3204 |
| Spray Machine | Airless spray, minimum 3500 psi at the spray gun head | Airless spray, minimum 3500 psi at the spray gun head |
| Transfer Pump | Minimum 3 gal/minute output | Minimum 3 gal/minute output |
| Hose Type | Minimum internal diameter of 3/4"; Moisture resistant hoses & fittings | Minimum internal diameter of 3/4"; Moisture resistant hoses & fittings |
| Spray Gun | 5,000 psi; reverse-a-clean tip | 5,000 psi; reverse-a-clean tip |
| Gun Tip | Minimum orifice of .030 and a 50° fan tip | Minimum orifice of .030 and a 50° fan tip |
| Mixing Info | Mix for 15 minutes upon opening, mix for 5 minutes every 1 hour thereafter. | Mix for 15 minutes upon opening, mix for 5 minutes every 1 hour thereafter. |
| Cure Time | 1-4 hours | 1-4 hours |
| Substrates | Metal, Modified Bitumen, BUR, TPO, PVC, Hypalon, Silicone | Spray Foam, Silicone |
| Storage: Sealed | Keep sealed at all times when not in use; store between 40° and 80°F in a dry place | Keep sealed at all times when not in use; store between 40° and 80°F in a dry place |
| Storage: Open | Reseal immediately when not in use. Follow instructions above. | Reseal immediately when not in use. Follow instructions above. |